

Please note it is likely that there is:  
 \*TELUS installed underground within the right of way, or on the powerpoles to be confirmed by the successful consultant.  
 \*ATCO gas installed underground within the right of way, to be confirmed by the successful consultant.  
 \*FIBER installed on the powerpoles, to be confirmed by the successful consultant.

**Water Lines**

- Needs Classification
- Supply Line
- Abandoned
- Distribution Main Line
- Hydrant Service Line
- Water Service Line

**Sewer Lines**

- Needs Classification
- Abandoned
- Force Main
- Gravity Main
- Service Lateral

- Fortis Poles
- Fortis Streetlights



Figure 3.0 - Existing Infrastructure



1: 1,250

Created By: Enter your name

Created On: Sep 01, 2020

Notes:

Disclaimer This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.  
**THIS MAP IS NOT TO BE USED FOR NAVIGATION OR LEGAL PURPOSES**



© Parkland County